

Beck glass top assembly instructions






Glass top assembly instructions:

Tools required:

- HK-261 enclosed hardware kit
- Screwdriver

1. With the table sitting flat on the floor, right side up, use the enclosed neoprene pad to remove the low profile caps that are holding the false top in place.
(Figure A)
2. Remove the false top and lay it on the floor with the routed cuts on the top side, like shown below. Set the table legs down in the routes. This will help hold the leg assembly in place.
(Detail B)

**FIGURE A****DETAIL B**
SCALE 1:10

Glass top assembly instructions, cont.:

Tools required:

- HK-261 enclosed hardware kit
- Screwdriver

3. Set the glass top in place over the stand off studs on top of the legs. Use the neoprene pad to tighten the low profile caps back in place.
4. On 42", 54" & 60" units, add (2) of the 3" screws from the hardware kit "HK-261" to the bottom of each leg where the predrilled holes are located. **(Detail A)** One leg will already have a screw in it.
5. Remove the table from the false top/form on the floor. The form can be discarded. Tip the table carefully and screw the levelers/glides back into the bottom of each leg.
6. Move the table to its desired location and level.

